L Number	Hits	Search Text	DB	Time stamp
21	19	(310/61.CCLS. or 310/65.CCLS. or	USPAT;	2002/12/10 17:48
		310/264.ccls. or 310/270.ccls.) and	EPO; JPO;	
	1	@pd>20020709	DERWENT;	
			IBM TDB	
25	5	("2980757" "3437859" "4297606"	USPAT	2002/12/10 17:50
		"5355046" "5869912").PN.		
30	7	("2778959" "2844746" "2904708"	USPAT	2002/12/10 17:50
		"5644179" "6204580" "6252318"		
		"6339268").PN.		
31	29	("1927890" "2653255" "2661434"	USPAT	2002/12/10 17:51
		"2724064" "2786951" "2796540" "2833944" "2844746" "2904708"		
		"2833944" "2844746" "2904708" "3005119" "3225231" "4071790"		
		"4141669" "4301386" "4335324"		
		"4415822" "4543503" "2920219"		
		"4922147" "5281877" "5644179"		
		"5685063" "6204580" "6252318"		
		"6339268" "6339269" "6362545"		la de la companya
-		"6392326" "6417586").PN.		
22	198	(motor and rotor and winding and block)	USPAT;	2002/12/10 17:52
		and @pd>20020709	EPO; JPO;	
		*	DERWENT;	
1			IBM TDB	. 1
_	2	("5644179").PN.	USPĀT;	2001/12/18 19:56
]			EPO; JPO;	·
1			DERWENT;	
			IBM_TDB	
-	16	("1819860" "2425997" "2786951"	USPAT	2001/12/18 19:56
		"2833944" "2844746" "3225231"		
		"3465183" "3846651" "4335324"		
		"4365177" "4415822" "4486676"		
		"4546279" "4656382" "4709177"		· · · · · · · · · · · · · · · · · · ·
	4	"5252880").PN.		0001/10/10 10 70
-	12	5644179.URPN.	USPAT	2001/12/18 19:59
_	12	("1927890" "2786951" "2787721" "2833944" "3225231" "4031422"	USPAT	2001/12/18 19:59
		"4335324" "4543503" "4546279"		
		"4709177" "4922147" "5644179").PN.		
_	0	6252318.URPN.	USPAT	2001/12/18 20:00
_	16	("2786951" "3225231" "4031422"	USPAT	2001/12/18 20:01
		"4071790" "4141669" "4301386"		
		"4335324" "4352034" "4546279"		
		"4922147" "4967465" "5252880"		
	\	"5281877" "5593274" "5644179"	1	
		"5929550").PN.		
-	239	(310/65).CCLS.	USPAT;	2002/02/08 18:58
			EPO; JPO;	
			DERWENT;	
_	167	310/264 gglg	IBM_TDB	2002/02/02 12 11
-	10/	310/264.ccls.	USPAT; EPO; JPO;	2002/02/08 19:14
		· ·		
			DERWENT; IBM TDB	
_	7	(((310/61).CCLS.) or ((310/65).CCLS.) or	USPAT;	2002/02/08 19:14
	,	310/264.ccls.) and ((space or cavity) near	EPO; JPO;	2002/02/00 19.14
		winding)	DERWENT;	
1		,	IBM TDB	
_	3	("2904708").PN.	USPAT;	2002/02/08 19:12
	1		EPO; JPO;	-51-, 52, 55 12.12
			DERWENT;	
			IBM TDB	
	7	(((310/61).CCLS.) or ((310/65).CCLS.) or	USPĀT;	2002/07/09 18:19
		310/264.ccls.) and scoop	EPO; JPO;	
		· ·	DERWENT;	
			IBM_TDB	
-	568	(310/61).CCLS.	USPAT;	2002/02/08 19:16
			EPO; JPO;	
			DERWENT;]
	L		IBM TDB	

_	33	motor and rotor and winding and block and	USPAT;	2002/12/10 17:47
	1	scoop	EPO; JPO;	1
			DERWENT;	
			IBM_TDB	l i
-	1	5757094.URPN.	USPAT	2002/02/08 19:31
_	11	("3819965" "4072872" "4442371"	USPAT	2002/02/08 19:32
		"4609840" "4766337" "5081384"		1
		"5177385" "5214324" "5306972"		1
		"5343101" "5757094").PN.		Į Į
_	11	(310/61.CCLS. or 310/65.CCLS. or	USPAT;	2002/12/10 17:46
		310/264.ccls.) and @pd>20011218	EPO; JPO;	
			DERWENT;	
			IBM TDB	
-	15	("2425997" "2778959" "2786951"	USPAT	2002/07/09 18:20
		"2833944" "2844746" "2904708"		
		"3225231" "4335324" "4546279"		
	`	"4709177" "5252880" "5644179"		
		"6204580" "6252318" "6339268").PN.		1
-	331	310/270.ccls.	USPAT;	2002/07/09 18:21
			EPO; JPO;	
			DERWENT;	
			IBM TDB	